

# General Environmental Incident Summary

**Incident:** 1973      **Date/Time Notice:** 7/8/2013      0900      **DEM Incident No:**

**Responsible Party:** Pat's Off-Road

**Date Incident:** 6/10/2013      **Time Incident:** 2355      **Duration:** 45 minutes

**County:** Williams      **Twp:** 154      **Rng:** 102      **Sec:** 23      **Qtr:**

**Lat:** 48.14728      **Long:** -103.76590      **Method:** Derived from TRS

**Location Description:** 14237 Hwy 2 West, Williston, ND or about 7 miles west of Williston on the north side of Hwy 2 at Pat's Off-Road a frac heating company.

**Submitted By:**

**Affiliation:**

**Address:**

**City:**

**State:**

**Zip:**

**Received By:** Brad Torgerson

**Contact Person:** Cale Kaup  
14237 Hwy 2 West  
Williston, ND 58801

**Distance Nearest Occupied Building:**

**Type of Incident:** Butterfly Valve Leak on 3" pipe under Acid Tanker

**Description of Released Contaminant:** Hydrochloric Acid

**Volume Spilled:** 500.00 gallons

**Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown

**Reported to NRC:** Unknown

**Cause of Incident:**

Valve Leak

**Risk Evaluation:**

Unknown

**# of Fatalities:** 0

**# of Injuries:** 0

**Affected Medium:** 03 - soil

**Potential Environmental Impacts:**

Acid impacted soils and potentially acid impacted stormwater and/or groundwater.

**Action Taken or Planned:**

Covered acid impacted soil with soil

**Wastes Disposal Location:** No disposal

**Agencies Involved:**

## ***Updates***

---

***Date:*** 7/8/2013

***Status:*** Reviewed; Followup Required

***Staff:*** Roberts, Kris

***Updated Volume:***

***Notes:***

Will need full report on this incident. Particularly what was done to neutralize the acid, where it ran to, and why it is just being reported now.